## Raytheon

## **ECS Project**

## **Engineering Technical Directive**

No. 01-010

Subject: AMASS to ACSLS Communications 19-Sep-01
The following directive is issued to all DAACS and labs.

**Issue:** In ECS 6A.04 and later, there appears to be a conflict in sockets between the

custom code and AMASS to ACSLS communications. No changes to ACSLS are

required.

Fix: This ETD changes the default AMASS socket connection from the AMASS

libsched daemon to the STK ssi daemon running on the SGI.

**Testing:** After modifications, verify that AMASS communicates with ACSLS by copying

at least one file to AMASS and one file from AMASS.

**Implementation:** 1. Schedule an outage of 30 minutes per host.

2. At the scheduled outage time, login to the AMASS SGI host and su to root

3. Edit the /usr/amass/.juke/config\_file\_1 to make XDI\_SSI\_SOCKET=1001

4. Edit the /usr/amass/.juke/config\_file\_2 to make XDI\_SSI\_SOCKET=1002

5. Edit the /etc/init.d/stk\_1 file to change the line (changes in **bold**): /usr/bin/ssi\_daemon\_1 \$curpid **60005** 23 2> /dev/null &

to

/usr/bin/ssi\_daemon\_1 \$curpid 1001 23 2> /dev/null &

6. Edit the /etc/init.d/stk\_2 file to change the line:

/usr/bin/ssi\_daemon\_1 \$curpid 60006 23 2> /dev/null &

to

/usr/bin/ssi\_daemon\_1 \$curpid 1002 23 2> /dev/null &

7. MAKE SURE NO ONE IS USING AMASS!!! Then restart the ssi daemons using the commands ( $\bot =$  press enter):

# /etc/init.d/stk\_1 stop ¿

# /etc/init.d/stk\_1 start ¿

# /etc/init.d/stk\_2 stop ¿

# /etc/init.d/stk\_2 start ¿

8. Stop AMASS using the command:

# /usr/amass/tools/killdaemons -f -t 0 ¿

9. After AMASS has stopped, restart using the command:

# /usr/amass/tools/amass\_start ¿

10. Verify that AMASS works by copying a file to AMASS and from AMASS.

11. Repeat procedure for each AMASS SGI.

**Point of Contact:** Byron V. Peters, email <u>bpeters@eos.hitc.com</u>

Phone: 301/883-4077

Approved By: V. Maclin

Director, Systems Engineering

Reference CCR: 01-0738

-----End of Directive-----